

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20232768
Address: 810 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|----------------------------------|------------|----------|--------------------------|
| Rated Assembly Inspection | Robb Popp | Partial | Monday, October 07, 2024 |

Corrective Action Required:

| | | |
|---|---------------|---|
| 1 | STAIR TOWER 1 | Stair in building F -1st land 2nd ayer behind stringers only at all floors |
|---|---------------|---|

Corrective Action Required:

| | | |
|---|---------------|--|
| 2 | STAIR TOWER 2 | -Stair in building G -1st and 2nd layer behind stringer only floors 1-4 |
|---|---------------|--|

Corrective Action Required:

| | | |
|---|---------------|----------------------------|
| 3 | STAIR TOWER 3 | Stair 3 in Building J (J2) |
|---|---------------|----------------------------|

Corrective Action Required:

| | | |
|---|---------------|--|
| 4 | STAIR TOWER 4 | Stair 4 in Building J: -1st and 2nd layer at stringer side only floors 1-3 -1st layer at 4th floor |
|---|---------------|--|

Corrective Action Required:

| | | |
|---|---------------|--|
| 5 | STAIR TOWER 5 | |
|---|---------------|--|

Corrective Action Required:

| | | |
|---|------------|--|
| 6 | ELEVATOR 1 | -1st and 2nd layer unit side behind trusses -1st, 2nd and 3rd layer at ceiling -Hat channel at ceiling -1st and 2nd layer interior all floors |
|---|------------|--|

Corrective Action Required:

| | | |
|---|------------|--|
| 7 | ELEVATOR 2 | |
|---|------------|--|

Corrective Action Required:

8

FIRST FLOOR

Building F:

-1st layer at truss space at firewall, stairwell and elevator for trusses at corridor side only

Building G:

-1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only

Corrective Action Required:

9

SECOND FLOOR

Building F:

-1st layer at truss space at firewall, stairwell and elevator for trusses at corridor side only

-1st layer behind tubs and showers

Building G:

-1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only

Corrective Action Required:

10

THIRD FLOOR

Building F:

-1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only

-1st and 2nd layer behind tubs and showers

Building G:

-1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only

Corrective Action Required:

11

FOURTH FLOOR

Building F:

-1st layer at truss space at firewall, stairwell and elevator for trusses at corridor side only

-1st and 2nd layer behind tubs

Building G:

-1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only

Comments: