CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20241766 Address: 2066 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Robb Popp	Failed	Tuesday, October 08, 2024
Corrective Action Required:			
1 Misc	 -lib's to be installed to plans - Requires 8' at garage side wall -provide attic access for ceiling space above garage-PROTECT ELECTRICAL WITHIN 6' OF ACCESS -uncover covered patio for inspection-INSTALL TRUSS HOLD DOWNS -missing multiple floor joists above dining room-MISSING (5) 2x4 stud pack -uncover sheathing at front entry to inspection nailing-PROVIDE JOIST HANGERS THROUGHOUT -strap top plates at front entry/dining room wall to adjoining-STRAP UPSTAIRS CONNECTION AS WELL -missing lateral bracing throughout m-C7 		

Comments: