

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20242665
Address: 3804 SW RAVENGATE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Kyle Beard	Failed	Friday, October 18, 2024

Corrective Action Required:

2	Miscellaneous Correction	3804 SW Ravengate. All rough (2) -Garage header jack studs have been over cut to allow electrical (electrical is now outside the stud space) -Patio door header to king stud has a 1/2 inch gap (caulking does not have structure strength) -Vertically support electrical wires to code between basement HVAC unit (not completed)
---	--------------------------	--

Comments: