CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20232768 Address: 810 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Rated Assembly Inspection		Robb Popp	Partial	Wednesday, October 30, 2024
Correctiv	e Action Required:			
1	STAIR TOWER 1	Stair in building F Complete		
Corrective Action Required:				
2	STAIR TOWER 2	-Stair in building G -1st and 2nd layer behind	stringer only floors 1-4	
	e Action Required:			
3 STAIR TOWER 3 Corrective Action Required:		Stair 3 in Building J (J2)		
4	STAIR TOWER 4	Stair 4 in Building J:		
		-1st and 2nd layer at strin	ger side only floors 1-3	
		-1st layer at 4th floor		
Corrective Action Required:				
5	STAIR TOWER 5	Stair at Building K		
Compati		-1st layer stringer side on	ly all floors	
Corrective Action Required:				
6	ELEVATOR 1	-1st and 2nd layer unit sic		
		-1st, 2nd and 3rd layer at -Hat channel at ceiling	cening	
		-1st and 2nd layer interio	r all floors	
Corrective Action Required:				
7	ELEVATOR 2	1st layer at ceiling		

Corrective Action Required: 8 FIRST FLOOR	Building F: -1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only -1st layer at 2 stairs and firewall -RC at walls and ceilings except 160,164,166
	Building G: -1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only
Corrective Action Required:	Building H: -1st and 2nd layer at truss spaces pre rock
9 SECOND FLOOR	Building F: -1st layer at truss space at firewall, stairwell and elevator for trusses at corridor side only -1st layer behind tubs and showers -1st and 2nd layer fire walls -RC at units and corridor
	Building G: -1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only
Corrective Action Required:	Building H: -1st layer at truss spaces pre rock
10 THIRD FLOOR	Building F: -1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only -1st and 2nd layer behind tubs and showers -1st layer at shear walls and 2 hour walls -RC at units and corridors -Screw pattern at units and corridor
	Building G: -1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only
Corrective Action Required:	Building H: -1st layer at truss spaces pre rock
11 FOURTH FLOOR	Building F: -1st layer at truss space at firewall, stairwell and elevator for trusses at corridor side only -1st and 2nd layer behind tubs -RC at units and corridor **Screw pattern at units and corridor except at elevator

Building G:

-1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only

Building H: -1st and 2nd layer at truss spaces pre rock

Building J: -1st and 2nd layer behind tubs and showers

Comments: