

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20242945  
Address: 3718 SW KNOXVILLE CT, LEES SUMMIT, MO 640823716 SW KNOXVILLE CT, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Kyle Beard	Failed	Tuesday, November 19, 2024

Corrective Action Required:

2	Miscellaneous Correction	3716 Holes are closer than 2 inches together at electrical in PFH north side leg (3) holes are within a 2 inch span and effect the structure support Vertical fire blocking is missing for 1/2 of king stud in garage at demising wall Fire rated roof sheathing at the ridge can have more than 1/4 of an inch gap (provide caulking information that was used) (2x4's used are not considered for fire rated assembly requirements)
		3718 Hole in vertical fire blocking in great room at demising wall (about 8 feet up from the floor) Provide more fire caulking around electrical service wire at demising wall for proper coverage and around electrical bonding wire

Comments: