

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20242945

Address: 3718 SW KNOXVILLE CT, LEES SUMMIT, MO 640823716 SW KNOXVILLE CT, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Kyle Beard	Failed	Monday, November 25, 2024

Corrective Action Required:

1	Miscellaneous Correction	3716 Holes are closer than 2 inches together at electrical in PFH north side leg (3) holes are within a 2 inch span and effect the structure support Vertical fire blocking is missing for 1/2 of king stud in garage at demising wall Fire rated roof sheathing at the ridge can have more than 1/4 of an inch gap (provide caulking information that was used) (2x4's used are not considered for fire rated assembly requirements)
---	--------------------------	--

3718

Hole in vertical fire blocking in great room at demising wall (about 8 feet up from the floor)

Provide more fire caulking around electrical service wire at demising wall for proper coverage and around electrical bonding wire

Corrective Action Required:

2	Miscellaneous Correction	Provide more fire caulking around electrical service wire at demising (rated assembly) wall for proper coverage and around electrical bonding wire
---	--------------------------	--

**Comments:**