CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20232768 Address: 810 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
All Rough Inspection - Commercial		Robb Popp	Partial	Wednesday, December 11, 2024
Corrective Action Required: 1 STAIR TOWER 1		Stair tower 1 in Building F: -Shear wall nailng pattern behind stringers at floors 1-3 *OK for first layer all floors inside of stairwell -1st layer all floors		
Corrective Action Required:				
2	STAIR TOWER 2	-Stair tower 2 in building -Shear wall nailing patter -Framing approved at all f	n behind stringers at floors	1-2
Correctiv	e Action Required:			
3	STAIR TOWER 3	-Stair tower 3 in building . -Shear wall nailing patter	J n behind stringers floors 1-	3
Correctiv	e Action Required:		-	
4	FIRST FLOOR	Building F Complete except as noted 157-NOT READY 389-Walls only ok-comple	d: ete meps at ceiling and seal	dead space
		Building G: -Behind tubs and showers -Balconies ok to cover -Complete HVAC at firew		

	149-Seal draft stop 2142-Bocca plates and seal penetrations at DWV, Seal dead spaces, strap load bearing walls, draft stop vertical at 10' oc, nail corners 421 and 422 not ready Mechanical closet-walls only ok to cover Maintenance garage- have engineer provide correction for (3) joist to beam where hanger is not connected Basement:- -Seal draft stops between garages, complete chase walls, furdowns and fireblocking
	Building H: -patios ok to cover -Behind tubs and showers ok to cover
Corrective Action Required	Building J: -Balconies ok to cover -Behind tubs and showers ok to cover
Corrective Action Required: 5 SECOND FLOOR	Building F: Complete except as noted: -Units and corridor complete
	Building G: -Behind tubs and showers for pre rock -Balconies ok to cover 224-complete chase wall and fireblocking at riser
	Building H: -patios ok to cover -Behind tubs and showers ok to cover
Course strikes Austriana Dominiana da	Building J: -Balconies ok to cover -Behind tubs and showers ok to cover
Corrective Action Required: 6 THIRD FLOOR	*Building F -Units and corridor approved
	Building G: -Behind tubs and showers for pre rock -Complete HVAC at firewall -Balconies ok to cover
	Building H: -patios ok to cover -Behind tubs and showers ok to cover
	Building J:

Corrective Action Required:	-Balconies ok to cover -Behind tubs and showers ok to cover
Corrective Action Required: 7 FOURTH FLOOR	*Building F -Units and corridor approved
	*Building G: Units and corridor complete -Balconies ok to cover
	Building H: -South side patios ok to cover -Behind tubs and showers ok -Patios ok to cover
Corrective Action Required:	Building J: -Balconies ok to cover -Behind tubs and showers ok to cover
Corrective Action Required: 8 ELEVATOR 1	Interior framing ok all floors
Corrective Action Required: 9 ELEVATOR 2	Elevator in G: Framing approved

Comments: