CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20244472Address:3900 SW FLINTROCK DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

n:	Inspector:	Outcome:	Date:
Inspection - al	Kyle Beard	Failed	Wednesday, December 18, 2024
Action Required:			
Miscellaneous Correction	Builder asked for garage PFH inspection only		
	-Exterior sheathing hold down straps are not installed and nailed off -Interior hold down straps were either covered or not installed -Interior PFH anchor bolts were not fully installed		
Action Required	Repair of replace damaged silt fence for proper erosion control before scheduling any more inspection (address erosion control inspection)		
2 Miscellaneous Correction	REQUESTED INSPECTION(S) DENIED DUE TO DEFICIENT EROSION CONTROL INSTALLATION.		
	See erosion control inspection on 11/20/24 and all rough inspection dated 11/20/24		
	Inspection - al Action Required: Miscellaneous Correction	Inspection - al Action Required: Miscellaneous Correction -Exterior sheathing hold d -Interior hold down straps -Interior PFH anchor bolts Repair of replace damaged scheduling any more inspection Correction Action Required: Miscellaneous Correction See erosion control inspection	Inspection - alKyle BeardFailedAction Required: Miscellaneous CorrectionBuilder asked for garage PFH inspection only -Exterior sheathing hold down straps are not installed -Interior hold down straps were either covered or no -Interior PFH anchor bolts were not fully installedAction Required: Miscellaneous CorrectionRepair of replace damaged silt fence for proper erosi scheduling any more inspection (address erosion con INSTALLATION. See erosion control inspection on 11/20/24 and all row

Comments: