

Corrective Action Required:

3 THIRD FLOOR

**Addition side:

*Ok to top out for MEPs throughout

3E-104, 3E-209A, 3E-209B, 3E-211

3E-311 to 3E-323, 3E-326, 3E-335, 3E-350 to 3E-369, 3E-252 to 3E-255, 3E-257 to

3E-261, 3E-214-230, 3E-302-308, 3E-103, 3E-233, 3E-232, 3E-250'

-South exterior framing ok cover

-Elevator infill walls

-North stairwell walls ok

Comments: