



# LEE'S SUMMIT, MISSOURI FIRE DEPARTMENT LOSS REDUCTION PROGRAM



## NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

CHANGES

<b>BUSINESS NAME</b>	REJUVENATE		
<b>ADDRESS</b>	400 SW LONGVIEW BLVD, Unit:160, LEES SUMMIT, MO 64081		
<b>OWNER/OPERATOR NAME</b>	HOFFMAN CORTES CONTRACTING COMPANY:	<b>TELEPHONE</b>	(816) 842-6170
<b>ADDRESS</b>	1600 BALTIMORE, STE 102 KANSAS CITY, MO 64108 Primary: (816) 842-6170 Cell: <NO CELL PHONE> LEON @ 816-365-0789		

### EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1. _____	_____
2. _____	_____
3. _____	_____
4. _____	_____

### LOSS REDUCTION TYPE

<input checked="" type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
<b>CLASS:</b> B	<b>Map#:</b> 194E	<b>PFA#:</b>	<b>KNOX BOX:</b>	<b>KNOX LOCATION:</b>	<b>PERMIT #</b> PRCOM20114294

### LOSS REDUCTION NARRATIVE

NO CORRECTIONS NOTED

ALL CORRECTIONS COMPLETED

Last Inspection                      1st Inspection 11/10/11                      2nd Inspection 11/15/11                      3rd Inspection                      4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
<b>Occupancy Inspection - Fire</b>	Joe Dir	Passed	Tuesday, November 15, 2011
Corrective Action Required: 2                      9/15/11: re-inspection found all issues corrected			
<b>Alarm Test</b>	Joe Dir	Passed	Thursday, November 10, 2011
<b>Sprinkler - Hydrostatic Test</b>	Joe Dir	Not Required	Thursday, November 10, 2011
<b>Sprinkler - Flow Test</b>	Joe Dir	Not Required	Thursday, November 10, 2011

**Occupancy Inspection - Fire** Joe Dir

Temporary C of O Thursday, November 10, 2011

Corrective Action Required:

- 1 (1) install sprinkler head eschution rings as neded throughout
- (2) cover all open j-boxes in ceiling at the front reception area. light fixtures to be installed later
- (3) mount fire extinguisher to wall in the rear -mid office area.

DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
November 15, 2011	Joe Dir	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	