

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20245649
Address: 1913 SW HIGHTOWN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Kyle Beard	Failed	Thursday, January 09, 2025

Corrective Action Required:

1	Miscellaneous Correction	- Panel splice for the PFH is located in the wrong area. - 2018 IRC states that a PFH panel splice should be located within the middle 24 inches of the portal leg R692.10.6.1
---	--------------------------	---

This was a partial all rough inspection for the garage portal framing only

Comments: