CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20242860 Address: 1438 SW WINTHROP TER, LEES SUMMIT, MO 640811436 SW WINTHROP TER, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
Rated Assembly Inspection		Kyle Beard	Failed	Monday, January 13, 2025	
Correcti	ve Action Required:				
1	Miscellaneous				
	Correction	1436			
		vertical screws are missing above primary bathroom			
			screw pattern along the rafters edge at demising wall is missing (6-8 inches on center) in the garage		
			Basement rim joist screw pattern along the edges should be every 6-8 inches		
		1438			
		Screw pattern along the rafters edge at demising wall is missing (6-8 inches on center) in the garage			
		Basement rim joist : center	Basement rim joist screw pattern along edges should be every 6-8 inches or center		
		This is a partial rate	d assembly inspection on	ly	

Comments: