

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20230407
Address: 1204 NE WOODS CHAPEL RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|-----------------------------------|------------|----------|----------------------------|
| Erosion Control Inspection | Nick Scott | Partial | Saturday, January 25, 2025 |

Informational:

| | | |
|---|------|---|
| 1 | Misc | Orchard woods 12-18-23 NS Site Visited and no erosion control issues 12-20-23 NS Site Visited and no erosion control issues 12-22-23 NS Site Visited and no erosion control issues 12-28-23 NS Site Visited and no erosion control issues 1-3-24 NS Site Visited and no erosion control issues 1-23-24 NS Site Visited and no erosion control issues 3-29-24 NS Site Visited and no erosion control issues 4-18-24 NS Site Visited and no erosion control issues 4-30-24 NS Site Visited and no erosion control issues 6-28-24 NS Site Visited and no erosion control issues 7-25-24 NS Site Visited and no erosion control issues 8-8-24 NS Site Visited and no erosion control issues 8-22-24 NS Site Visited and no erosion control issues 9-30-24 NS Site Visited and no erosion control issues 10-14-24 NS Clean out detention basin fix silt fence around job area clean the roads off of any dirt or debris Put grass seed down 10-31-24 NS Site Visited and nothing has been fixed since last inspection. 11-6-24 NS now work has been done to correct problem 11-13-24 NS Site Visited gutter buddies need to be cleaned out. |
|---|------|---|

12-13-24 NS Site Visited and still no erosion control issues
12-31-24 NS Site Visited and still no erosion control issues
1-10-25 NS Site Visited and still no erosion control issues
1-16-25 NS Site Visited and still no erosion control issues
1-24-25 NS Site Visited and still no erosion control issues

Comments: