

1499 SW MARKET

TLO

Mark Harding

From: Bruce Best [bruce@agmparch.com]
Sent: Tuesday, October 11, 2011 8:45 AM
To: Mark Harding
Subject: Re: 1499 SW MARKET
Attachments: TF-2.3 Revised.pdf; ATT00001.txt

Note:

All Interior Walls Are Shown W/ MTL
Studs, Wood Studs Are NOT AN
Approved Alternate Code.

Note;
2'-0"± Elevation Change,
Field Verify

Exist 2-HR Building
Separation Fire Wall.

Owner Supplied Constractor
Installed Elec. Chair Lift. From
Natal Wheel•O•Vator Vert.
Platform Lift, Secure To Conc. Floor.
Per MFG Req'ds. & Supply Side
Walls And Electrical Power Per
MFG Requirements. (Refer To
Attached MFG Sheets.)

Wood Or MTL Stairs & Landing

Wall MTD And Or Floor
Supported MTL Hand Rail /
Guard Rail

New Partition Wall Per Plan.

Extend Side Walls Per MFG
Requirements.

9'-8 1/4"
Field Verify

7 ENLARGED STAIR PLAN

Scale 1/2" = 1'-0"

