CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20232768 Address: 810 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Rated Assembly Inspection		Robb Popp	Partial	Thursday, February 06, 2025
Correctiv	ve Action Required:			
1	STAIR TOWER 1	Stair in building F Complete		
Corrective Action Required:				
2	STAIR TOWER 2	-Stair in building G Complete		
Correctiv	ve Action Required:			
3	STAIR TOWER 3	Stair 3 in Building G -Complete		
Corrective Action Required:				
4	STAIR TOWER 4	Stair 4 in Building J: complete		
Corrective Action Required:				
5	STAIR TOWER 5	Stair at Building K -1st layer stringer side on	ly all floors	
Correctiv	ve Action Required:			
6	ELEVATOR 1	 -1st and 2nd layer unit side -1st, 2nd and 3rd layer at -1st and 2nd layer interio -1st, 2nd layer at unit side -1st and 2nd layer inside 	ceiling r all floors e	
Correctiv	ve Action Required:			

7	ELEVATOR 2	1st layer,2nd, 3rd layer and hat channel at ceiling 1st and 2nd layer all floors interior 3 walls -1st and 2nd layer outside all floors -1st and 2nd layer inside at 4th, 2nd, 1st floors
Correctiv 8	e Action Required: FIRST FLOOR	Building F: complete
		Building G: -1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only -1st and 2nd layer behind tubs and showers -1st and 2nd layer at 2 hr walls -Screw pattern complete except at 421 & 422
		Building H: -1st and 2nd layer at truss spaces pre rock -1st and 2nd layer at firewall extensions at deck -1st and 2nd layer behind tubs -1st and 2nd layer at firewalls -Screw pattern at walls and ceiling
Corrective 9	e Action Required: SECOND FLOOR	Building J: -1st and 2nd layer behind tubs and showers -1st layer at pet SPA
		Building F: Complete
		Building G: Complete
		Building H: -1st layer at truss spaces pre rock -1st and 2nd layer at firewall extensions at deck -1st and 2nd layer behind tubs - 2nd layer fire tape and mud at top plate of fire walls -RC at units and corridor -Screw pattern units and corridor
Corrective 10	e Action Required: THIRD FLOOR	Building J: -1st and 2nd layer behind tubs and showers
		Building F: Complete
		Building G: Complete
		Building H:

	 -1st layer at truss spaces pre rock -1st and 2nd layer at firewall extensions at deck -1st layer at firewalls and shear walls - 2nd layer fire tap and mud top plate at fire walls -RC at units and corridor -1st layer at 2 hour walls
	Building J: -1st and 2nd layer behind tubs and showers
Corrective Action Required: 11 FOURTH FLOOR	Building F: Complete
	Building G: -1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only -Pre-rock 2nd layer behind showers at units 2424,2426,2434, and 2435 -1st layer at firewalls **Screw pattern at units and corridor except at elevator
	Building H: -1st and 2nd layer at truss spaces pre rock -1st and 2nd layer behind tubs and showers -1st and 2nd layer at firewall extensions at deck -RC at units and corridor except at fire walls ok -1st and 2nd layer at 2 hour walls -Screw pattern at units and corridor
	Building J: -1st and 2nd layer behind tubs and showers -RC at units and corridors
Corrective Action Required: 12 ELEVATOR 3	-1st and 2nd layer at (3) interior walls -1st, hat channel 2nd and 3rd layer at ceiling
Corrective Action Required: 13 LOWER LEVEL	RC at G,H,J approved 1st layer at G,H,J firewalls

Comments: