CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20242328

Address: 3505 SE CORBIN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Occupancy Inspection - Codes Kyle Beard Not Ready Tuesday, February 11,

Residential 2025

Corrective Action Required:

1 Miscellaneous EROSION CONTROL REQUIRED. NO FURTHER INSPECTIONS WILL BE Correction PERFORMED UNTIL EROSION CONTROL IS INSTALLED AND IN COMPLIANCE.

- Front waddles are damaged and or missing in spots and are not longer effective
- Spoil pile in the backyard does not have erosion control around it
- House is not ready for an occupancy inspection due to no exterior garage lights being installed and No guard rail being installed at the front porch.

THIS IS NOT A COMPLETE LIST

Walk your property before scheduling your inspections

Comments: