CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20244613

Address: 3445 SE CORBIN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Erosion Control Inspection Kyle Beard Failed Tuesday, February 11,

Residential 2025

Corrective Action Required:

2 DCM1 ESC EROSION CONTROL REQUIRED. NO FURTHER INSPECTIONS WILL BE REQUIRED NO PERFORMED UNTIL EROSION CONTROL IS INSTALLED AND IN COMPLIANCE. FURTHER INSP

- Erosion control measures at the front of the lot are either missing and or $% \left\{ 1\right\} =\left\{ 1\right$
- torn down in areas
 Dirt spoil pile does not have erosion control around it
- -NO ADDRESS POSTED

Comments: