CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20245539

Address: 1625 SW ARBORWAY TER, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Kyle Beard Not Ready Wednesday, February

Residential 12, 2025

Informational:

1 Misc Exterior garage PFH and Front exterior only ok to cover

Corrective Action Required:

Miscellaneous -Missing fire blocking in top plate around garage double overhead door (both

Correction sides)

-Fasten exterior sheathing to code at front entry to garage wall by Ibeam

-Fire block top of chases in garage

Install anchor bolts in garage west bottom plate to code

-Secure base of steel column post in garage

-3 inch DWV above garage is not completed

-4 inch hole in floor above the garage

-Second set of 2x6 studs are not installed along garage west wall

-LIB's in garage are not installed

House is not ready for inspection

Walk your property before scheduling your inspections

Not a complete list

Comments: