CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20245422

Address: 3207 SW ARBOR SOUND DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Friday, February 14,

Residential 2025

Informational:

1 Misc Garage portal frame nailing inspection only- OK

Corrective Action Required:

2 Misc

- -seal top plate penetration in between garage doors
- -protect NM within 6' of attic access
- -nail plate under header at garage portal into header
- -provide attic access above single car garage
- -address missing stud at garage/foyer
- -anchor bolts to be in the middle 1/3 of sill plate (see garage doors)
- -seal top plate penetration at garage entry
- -seal dead space to ceiling space at laundry
- -seal top plate penetration at primary bath
- -seal dead space at stairwell
- -provide strapping to plans at primary bedroom windows
- -plans call for continuous header at rear great room windows and side dining room window
- -missing lib in bed 2
- -missing lateral bracing on multiple trusses throughout
- -missing IvI NE basement
- -provide future vent for basement bath

Comments: