CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20242627

Address: 3509 SE CORBIN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Occupancy Inspection - Codes Kyle Beard Failed Monday, February 24,

Residential 2025

Corrective Action Required:

1 Miscellaneous Front porch guard rail is not installed Correction Front door secondary lock is not installed

Back yard security light is not installed and has exposed wires

Receptacle in powder bathroom is not working Garage to house door seal is not installed

Fire block gaps in sheet rock above garage overhead doors Front porch electrical receptacle is loose within plastic cover Final grading is not complete in areas for plot plan inspection

AC unit not installed Gutters are not installed

Sod and splash pads are not installed Sump pump extension is not installed

Driveway final is not finalized Sidewalk final in not finalized

Comments: