

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20231975

Address: 1600 SE HAMBLER RD, LEES SUMMIT, MO 64081
1600 SE HAMBLER RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Erosion Control Inspection Residential	Bobby Richest	Partial	Monday, December 02, 2024

Corrective Action Required:

1	Misc	5-21-24 BR Erosion control is up and working order.
		5-30-24 BR Erosion control is up and working order.
		6-3-24 BR Erosion control is up and working order.
		6-17-24 BR Silt fence needs to be repaired. There are several location along on the fence line that needs to be repaired.
		6-18-24 BR Silt fence has been repaired erosion control is up and working order.
		6-26-24 BR Erosion control is up and working order.
		7-3-24 BR Erosion control is up and working order.
		7-11-24 BR Erosion control is up and working order.
		7-17-24 BR Erosion control is up and working order.

7-26-24 BR Erosion control is up and working order.

8-9-24 BR Erosion control is up and working order.

8-15-24 BR Silt fence needs to be repaired. There are several location along on the fence line that needs to be repaired.

8-26-24 BR Silt fence needs to be repaired. There are several location along on the fence line that needs to be repaired.

9-5-24 BR Erosion control is up and working order

9-11-24 BR Erosion control is up and working order.

9-17-24 BR Erosion control is up and working order.

9-30-24 BR Erosion control is up and working order.

10-4-24 BR Erosion control is up and working order.

10-18-24 BR Erosion control is up and working order.

11-4-24 BR Erosion control is up and working order.

11-14-24 BR Erosion control is up and working order.

12-2-24 BR Erosion control is up and working order.

1-8-25 BR Erosion control is up and working order.

1-25-25 BR Erosion control is up and working order.

2-17-25 BR Erosion control is up and working order.

3-4-25 BR Erosion control is up and working order.

Comments: