

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20245637
Address: 4421 SW GRINDSTONE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mitchell Schwarz	Not Ready	Friday, March 07, 2025

Corrective Action Required:

1	Miscellaneous Correction	Note from inspection dated 02/11/2025 Exterior garage PFH sheathing failed inspection - Sheathing does not extend to both top plates. See bracing detailed in plans on page S530 illustration #5 This inspection was for a exterior garage PFH only - See failed erosion control (03/04/25) - See failed gas inspection (03/04/25) - Truss plans are not on site (3/04/25)
---	--------------------------	--

Corrective Action Required:

2	Misc	No complete truss packet on site for inspection -no city stamped plans on site for inspection
---	------	--

Comments: