

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816) 969-1200 FAX (816) 969-1201

Temporary Certificate of Occupancy

Permit #: PRRES20242381
Address: 2213 NW KILLARNEY LN, LEES SUMMIT, MO 64081
Inspected On: Tuesday, March 11, 2025
Inspected By: Development Center
Expiration Date: 3/13/2025 12:00:00 AM

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Residential	Robb Popp	Ready for Temp CO	Tuesday, March 11, 2025

Corrective Action Required:

1	Miscellaneous Correction	-Deck stair landing is not installed -Outside AC unit is not installed -Seal gap in siding to foundation wall along the east side -Front porch soffit is not complete -Sod, splash pads and sump pump extension are not installed -Plot plan could not be completed due to snow on the ground -Sidewalk inspection must pass -Re establish erosion control at front of lot
---	--------------------------	---

Occupancy Inspection - Codes Residential	Robb Popp	Ready for Temp CO	Tuesday, February 11, 2025
---	-----------	-------------------	----------------------------

Corrective Action Required:

1	Miscellaneous Correction	-Deck stair landing is not installed -Outside AC unit is not installed -Seal gap in siding to foundation wall along the east side -Front porch soffit is not complete -Sod, splash pads and sump pump extension are not installed
---	--------------------------	---

- Plot plan could not be completed due to snow on the ground
- Sidewalk inspection must pass
- Re establish erosion control at front of lot

**Occupancy Inspection - Codes
Residential**

Shawn Hoffman

Ready for Temp CO

Wednesday, January
22, 2025

Corrective Action Required:

1 Miscellaneous
 Correction

- Deck stair landing is not installed
- Outside AC unit is not installed
- Seal gap in siding to foundation wall along the east side
- Front porch soffit is not complete
- Sod, splash pads and sump pump extension are not installed
- Plot plan could not be completed due to snow on the ground
- Sidewalk inspection must pass
- Re establish erosion control at front of lot

Comments: