CITY OF LEE'S SUMMIT **Development Services Department** 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20245803

Address: 2805 SW HEARTHSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection -Mitchell Schwarz Failed Thursday, March 27,

Residential 2025

Corrective Action Required:

2 Misc -nail plate under header into header to code at pfh

-nail all intersecting exterior wall corners together to plans

-furr around for bath vent in garage

-furr down for insulation in garage where joist space filled by dwv

-address missing nails in hangers throughout kitchen

-provide security blocking at rear door

-fireblock wall space to ceiling space at fireplace

-missing nails in hanger for double IvI above owners suite

-fireblock owners bath wall space to ceiling space

-provide all NM within 6' of attic access 1st and 2nd floor

-protect dryer vent at top plate to code 1st and 2nd floor

-fireblock basement stairwell wall/flex room to ceiling space seal dead spaces

as well

-add studs at flex room closet where missing

-fireblock top or 2nd story stairwell wall to ceiling space

-provide appropriate hangers for joists above panel

-secure/support electrical run next to stairs in basement

-provide solid blocking under kitchen area to plans

_	
Comm	onter
COIIIII	iciits.