



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRSUBD20211138, Public Infrastructure
Address: 1201 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
PW Bond Inspection	Matt Munger	Passed	Monday, March 31, 2025

Corrective Action Required	
1 Misc	Bond Inspection - No major issues with the pavement. Passed.

Comments: