# CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

# **DEVSERVICES.CITYOFLS.NET**

# **Inspection Summary**

Permit #: PRRES20245048

Address: 2739 SW HEARTLAND RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Thursday, April 03,

Residential 2025

## Corrective Action Required:

2 Misc

- -missing straps at PFH
- -anchor bolts to be in the middle 1/3 of sill plate and Tight
- -block sheathing breaks throughout garage where missing
- -furr around for sub panel service cable in ceiling space
- -strap top plate and protect dryer vent at top plate
- -furr down for bath vent at garage entry bath
- -missing nails in multiple hangers above kitchen
- -address beam separating kitchen and great room connection not to plans
- and LVL Notched into I beam
- -fire block furr out wall 2nd story floor height right of fireplace
- -ensure stairways comply with code section R311.7 of the 2018 IRC
- -add full length studs where missing at stairway/exterior wall
- -address rafters landing on osb throughout 2nd floor
- -3 studs at each exterior wall corner in basement
- -address holes drilled in joist for hvac intake/exhaust
- -fire block dead spaces at basement bathroom with approved fire blocking material

### **Comments:**