

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRSUBD20210775, Public Infrastructure	
Address: 1201 SW LONGVIEW BLVD, LEES SUMMI ⁻	г, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

PW Bond Inspection Matt Munger Passed Tuesday, April 08, 2025

Corrective Action Required

1 Misc Bond Inspection - No major road defects at this time. Passed.

Comments: