



LEE'S SUMMIT, MISSOURI FIRE DEPARTMENT LOSS REDUCTION PROGRAM



NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

BUSINESS NAME	JOHN KNOX VILLAGE SOLAR ARRAY		
ADDRESS	400 NW MURRAY RD, LEES SUMMIT, MO 64081		
OWNER/OPERATOR NAME	BRIGHTERGY LLC:	TELEPHONE	(913) 735-9733
ADDRESS	15209 W 99TH ST LENEXA, KS 66219 Primary: (913) 735-9733 Cell: (206) 718-7416		

EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1.	
2.	
3.	
4.	

LOSS REDUCTION TYPE

<input type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: I-2	Map#:	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT #

LOSS REDUCTION NARRATIVE

☐ NO CORRECTIONS NOTED

☐ ALL CORRECTIONS COMPLETED

Last Inspection

1st Inspection

2nd Inspection

3rd Inspection

4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Occupancy Inspection - Fire		Temporary C of O	Friday, December 30, 2011
Corrective Action Required:			
1 Label breaker panel in basement mechanical room.			
Corrective Action Required:			
2 Label the inverter, inverter disconnects with address labels.			
Corrective Action Required:			
3 Required fireblocking and draftstopping in combustibile concealed spaces shall be maintained to provide continuity and integrity of the construction.			
Maint fire stopping in mechanical room per Codes Admin.			
DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE

December 30, 2011	Jim Eden	<input type="checkbox"/> Yes <input type="checkbox"/> No	
-------------------	----------	--	--