CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20231204 Address: 2951 SE SHENANDOAH DR, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Rated Assem	nbly Inspection	Khanh Nguyen	Failed	Thursday, April 17, 2025
Corrective Ac	tion Required:			
	isc	-wall inside lower level bat -2 hr floor assembly under Elevator shaft wall: -interior side-side and back -outer side-basement floor Corrections required: **Elevator fire barrier encl Complete patching and fire enclosure	guest suite side and stairwell side-2nd layer wall inside lower level bathroom and storage space under guest rm-2nd layer 2 hr floor assembly under guest suite levator shaft wall: nterior side-side and back walls only outer side-basement floor front wall orrections required: *Elevator fire barrier enclosure: outer side screw pattern was not inspected. omplete patching and fire caulking of the inside wall of elevator shaft nclosure *Protect penetrations (roof drainage and framing) of the 2-hr wall above gues	

Comments: