

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20245549
Address: 1933 SW MERRYMAN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Erosion Control Inspection Residential	Jamie Simerly	Failed	Thursday, April 24, 2025

Corrective Action Required:	
2 Misc	Erosion control in place at time of inspection
Corrective Action Required:	
3 DCM2 ESC DEFICIENT INSTALLATION	04/24/25 Jamie S, Silt fence is down on the front of the house. Replacement or repair required. Storm drain protection on the south of lot needs to be cleaned out. DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS UNTIL ADEQUATE EROSION CONTROL PROVIDED.

Comments: