## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRRES20244023Address:2748 SW 11TH TER, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Sidewalk Inspection		Devon Perry	Failed	Wednesday, April 30, 2025
Informatio	onal:			
1	Misc	shallow. Contractor corrected cross slopes white recompacted and made of Approved to pour. SW in compacted, cross slopes 3-18-25 DP. SW Infront of to pour. The SW that goed steep grade. The contracted 8.3%. It ranges from 8.5-4	<ul> <li>, SW was formed, aggregate compacted. Aggregate depth was too contractor corrected while I was onsite. After adjustments I oss slopes which were in compliance. Rock depth fixed and ed and made contractor lay out expansion joint for property line. to pour. SW in front of property was formed, aggregate I, cross slopes in compliance, approved to pour.</li> <li>. SW Infront of house was formed, aggregate compacted, approved ne SW that goes down the hill and meets up to existing SW has a e. The contractor rebuilt it 3 times and it initially starts out over nges from 8.5-8.8% but quickly gets under the 8.3% requirement. I the running slope after it is poured.</li> </ul>	
		3-25-25 DP. White cure was applied really poorly. This needs fixed		
		4-30-25 DP. White cure is	still not fixed	

Comments: