

Report Email:

Copy Email:

Lab Report Fax No: (816) 365-8086

Lab Report Contact 1: (816) 289-6818

Lab Report Contact 2: (816) 221-3500

Customer ID No: 8178

Customer PO No:

Collected By: Client

Invoice No: 63856

Accounts Payable

Emery Sapp and Sons, Inc.

140 Walnut

Kansas City, MO 64106

Report of Analysis

Laboratory Report ID No:

20778**Project Name:** Bailey Farms First Plat Tie-in Point

Item No.	Cat NO	ANALYSIS	COLLECTED	ANALYZED	REPORTING	LIMIT	RESULTS
	Line NO	SAMPLE TYPE	SAMPLE SITE NOTES		TEST METHOD		
1	6191	Bacteria, P/A E. Coli	5/1/25	5/2/25	1	CFU/100mL	Negative
	139995	Grab	Spot One Sample One		SM9223 B		CFU/100mL
2	6190	Bacteria, P/A T. Coliform	5/1/25	5/2/25	1	CFU/100mL	Negative
	139993	Grab	Spot One Sample One		SM9223 B		CFU/100mL

Comments, if present, concern this Lab Work Order:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without written approval by Blue Valley Laboratories, Inc.