



LEE'S SUMMIT, MISSOURI FIRE DEPARTMENT LOSS REDUCTION PROGRAM



NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

BUSINESS NAME	PILLARS OF TRUTH		
ADDRESS	653 SW 2ND ST, LEES SUMMIT, MO 64063651 SW 2ND ST, LEES SUMMIT, MO 64063		
OWNER/OPERATOR NAME	OBI CONSULTING ENGINEERS INC:	TELEPHONE	(816) 822-7292
ADDRESS	1220 E 63RD ST STE 200 KANSAS CITY, MO 64110 Primary: (816) 822-7292 Cell: <NO CELL PHONE> Emanuel @ 816-223-8966		

EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1.	
2.	
3.	
4.	

LOSS REDUCTION TYPE

<input checked="" type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: A-3	Map#: 195F	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT # PRCOM20116192

LOSS REDUCTION NARRATIVE

☐ NO CORRECTIONS NOTED

☐ ALL CORRECTIONS COMPLETED

Last Inspection

1st Inspection 1/12/12

2nd Inspection

3rd Inspection

4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Occupancy Inspection - Fire	Joe Dir	Temporary C of O	Thursday, January 12, 2012
Corrective Action Required: 1 (1) label all front and back dorrswith the same address (653) (2) supply (3) 2A-10BC extinguishers and mount in the locations as discussed (3) remove slide bolt locks from the rear doors and repair panic hardware (4) post an occupant load of (124) in the sanctuary			
DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
January 12, 2012	Joe Dir	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	