



CITY OF LEE'S SUMMIT  
CODES ADMINISTRATION  
220 SE GREEN ST.  
P.O.BOX 1600

PHONE:  
816-969-1200

FAX:  
816-969-1201

## Inspection Summary

---

Permit #: PRCOM20116192, Building Permit - Commercial  
Address: 653 SW 2ND ST, LEES SUMMIT, MO 64063651 SW 2ND ST, LEES SUMMIT, MO 64063

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>In-wall Inspection</b>	John Borns	Not Ready	Thursday, January 12, 2012

Corrective Action Required  
1 MISC

PARTIAL IN-WALL INSPECTION TO BE PERFORMED WHEN ACCESSIBLE

**Occupancy  
Inspection - Codes  
Commercial**

John Borns	Failed	Thursday, January 12, 2012
------------	--------	----------------------------

Corrective Action Required  
1 MISC

RESOLVE FIRE DEPARTMENT ISSUES

Corrective Action Required  
2 MISC

WATER UTILITIES DEPARTMENT INSPECTION (PARTICULARLY BACKFLOW PREVENTION AT MAIN ENTRY)

Corrective Action Required  
3 MISC

ELECTRICAL PANELS SCHEDULES: NEC 110-22; 384-13; IRC E3606.2: EACH BREAKER MUST BE LABELED WITH REFERENCE TO SPECIFIC SPACE(S) OR EQUIPMENT SERVED. MUST BE LEGIBLE; SPECIFIC. NO DITTO MARKS OR CONTINUATION SYMBOLS FOR INDIVIDUAL BREAKERS. LABEL UNUSED BREAKERS "SPARE"

Corrective Action Required  
4 MISC

ENSURE ALL ELECTRICAL RECEPTACLES ARE SECURED SOLID TO BOX

Corrective Action Required

5	MISC	ELECTRICAL RECEPTACLE AT SW RESTROOM IS NOT GFCI PROTECTED
Corrective Action Required		
6	MISC	ENSURE ALL ELECTRICAL RECEPTACLES AND SWITCHES HAVE FACE PLATES IN PLACE
Corrective Action Required		
7	MISC	"NO SMOKING" SIGNS TO BE AFFIXED TO PUBLIC ENTRANCE DOORS

<b>Occupancy</b>	Joe Dir	Temporary C of O	Thursday, January 12, 2012
<b>Inspection - Fire</b>			

Corrective Action Required	
1	MISC

(1) label all front and back doors with the same address (653)  
(2) supply (3) 2A-10BC extinguishers and mount in the locations as discussed  
(3) remove slide bolt locks from the rear doors and repair panic hardware  
(4) post an occupant load of (124) in the sanctuary

**Comments:**