



LEE'S SUMMIT, MISSOURI FIRE DEPARTMENT LOSS REDUCTION PROGRAM



NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

| | | | |
|---------------------|--|-----------|----------------|
| BUSINESS NAME | PILLARS OF TRUTH | | |
| ADDRESS | 653 SW 2ND ST, LEES SUMMIT, MO 64063651 SW 2ND ST, LEES SUMMIT, MO 64063 | | |
| OWNER/OPERATOR NAME | OBI CONSULTING ENGINEERS INC: | TELEPHONE | (816) 822-7292 |
| ADDRESS | 1220 E 63RD ST STE 200 | | |
| | KANSAS CITY, MO 64110 | | |
| | Primary: (816) 822-7292 | | |
| | Cell: <NO CELL PHONE> Emmanuel @ 816-223-8966 | | |

EMERGENCY CONTACT INFORMATION

| | |
|------|-----------|
| NAME | TELEPHONE |
| 1. | |
| 2. | |
| 3. | |
| 4. | |

LOSS REDUCTION TYPE

| | | | | | |
|---|--|---------------------------------|--|---------------------------------------|--|
| <input checked="" type="checkbox"/> Occupancy | <input type="checkbox"/> Semi-Annual | <input type="checkbox"/> Annual | <input type="checkbox"/> Life Safety | <input type="checkbox"/> Sprinkler | <input type="checkbox"/> Hazardous Material Permit |
| <input type="checkbox"/> Complaint | <input type="checkbox"/> Explosive Storage | <input type="checkbox"/> UST | <input type="checkbox"/> Post-Incident | <input type="checkbox"/> Open Burning | <input type="checkbox"/> Other |
| CLASS: A-3 | Map#: 195F | PFA#: | KNOX BOX: | KNOX LOCATION: | PERMIT # PRCOM20116192 |

LOSS REDUCTION NARRATIVE

☐ NO CORRECTIONS NOTED

☐ ALL CORRECTIONS COMPLETED

Last Inspection

1st Inspection 1/12/11

2nd Inspection 1/20/11

3rd Inspection

4th Inspection

| | | | |
|--|--|----------------------|----------------------------|
| INSPECTION | INSPECTOR | OUTCOME | DATE |
| Occupancy Inspection - Fire | Joe Dir | Passed | Friday, January 20, 2012 |
| Corrective Action Required: ALL PENDING ISSUES HAVE BEEN CORRECTED | | | |
| | | | |
| Occupancy Inspection - Fire | Joe Dir | Temporary C of O | Thursday, January 12, 2012 |
| Corrective Action Required: | | | |
| 1 | (1) label all front and back dorrs with the same address (653) | | |
| | (2) supply (3) 2A-10BC extinguishers and mount in the locations as discussed | | |
| | (3) remove slide bolt locks from the rear doors and repair panic hardware | | |
| | (4) post an occupant load of (124) in the sanctuary | | |
| DATE OF REPORT | INSPECTOR | PREVENTION FOLLOW-UP | RESPONSIBLE SIGNATURE |

| | | | |
|------------------|---------|--|--|
| January 20, 2012 | Joe Dir | REQUIRED? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | |
|------------------|---------|--|--|