# CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

# **DEVSERVICES.CITYOFLS.NET**

# **Inspection Summary**

Permit #: PRSUBD20236023

Address: 3201 NE WILSHIRE DR, LEES SUMMIT, MO 64064551 NE MEADOWVIEW DR, LEES SUMMIT, MO

640643200 NE WILSHIRE DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

**Erosion Control Inspection** Nick Scott Partial Wednesday, May 14,

2025

### Corrective Action Required:

1 Misc Retirement home

10-14-24 NS Gutter buddies need to be installed around construction site 10-31-24 NS Site Visited and no work has been done since last inspection

11-6-24 NS Site Visited and still no erosion control issues

11-13-24 NS Site Visited and still no erosion control issues

12-13-24 NS Site Visited and still no erosion control issues

12-31-24 NS Site Visited and still no erosion control issues

1-10-25 NS Site Visited and still no erosion control issues

1-16-25 NS Site Visited and still no erosion control issues

1-24-25 NS Site Visited and still no erosion control issues

1-31-25 NS Site Visited and still no erosion control issues

2-3-25 NS Site Visited and still no erosion control issues

2-10-25 NS Site Visited and still no erosion control issues

2-17-25 NS Site Visited and still no erosion control issues

2-24-25 NS Site Visited and still no erosion control issues

2-28-25 NS Site visited and it appears that no erosion control issues

3-6-25 NS Site visited and it appears that no erosion control issues

 $3-19-25\ NS$  Site visited and saw fence down and the company went out while

I was there.

4-3-25 NS Site visited and drove around jobsite and it appears that site does

not have a problem.

 $4-16-25\ NS\ Site\ visited\ and\ it\ appears\ concrete\ spilled\ and\ the\ crew\ is\ cleaning\ it\ up.$ 

4-24-25 NS Site visited and it appears that jobsite has no problems

## **Comments:**