## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20235207

Address: 2931 SE SHENANDOAH DR, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Khanh Nguyen Failed Thursday, May 15,

Commercial 2025

Corrective Action Required:

1 Misc Front garage PFH walls only:

-Provide 2 anchors per wall sill plate

-Nail wall top plate to header w/ 2 rows of 16d @ 3" oc

Corrective Action Required:

2 Misc Interior and exterior sheathed shearwalls:

-lower level, 1st, and 2nd fl-one side sheathed

-exterior shearwalls

Corrective Action Required:

3 LOWER LEVEL -Pre-rock behind tubs ad showers

Corrective Action Required:

4 FIRST FLOOR -Pre-rock behind tubs ad showers

Corrective Action Required:

5 SECOND FLOOR -Pre-rock behind tubs ad showers

Corrective Action Required:

6 THIRD FLOOR

Corrective Action Required:

7 FOURTH FLOOR \*\* = check all units

\*\*Draft-stop roof space per A1.07. Fire block all holes, gaps, and penetrations

of draft-stop

	-Tie down rafters above bathroom
	403, 404, 411, 412-Install firestop at roof drain floor&ceiling penetrations per Hilti Instructions
Comments:	

402: