CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20240118

Address: 515 NW MOORE ST, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Retaining Wall Inspection Robb Popp Partial Friday, June 06, 2025

Informational:

1 Misc 06/05/25 Thursday JMJ (Gen. Struad, Sub. Hardscape)

Contractor did not contact inspector at the beginning of installation. Inspector took picture of the retaining wall today and talked again to the general contractor about notifying inspector, so work can be properly

inspected.

06/06/25 Friday JMJ (Gen. Struad, Sub. Hardscape)

Hardscape uninstalled retaining wall due to some deficiency. Inspector has

taken photos of retaining wall which was completely deconstructed.

Hardscape was work survey and grading to began reconstruction of retaining

wall.

Comments: