## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 OnlinePortal at DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #: PRRES20251486 Address: 1043 SW FIORD DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
All Rough Inspection - Residential		Shawn Hoffman	Failed	Tuesday, June 24, 2025	
Correc	tive Action Required:				
5	Misc	1043 sw fiord FB = Fire Block			
		- Missing LUS24 hange	Missing LUS24 hangers on trusses at front porch ( now covered)		
		<ul> <li>Fb top of chase garage fur out to soffit at pantry</li> <li>Fb end of soffit near pantry</li> <li>Anchor support under I-beam at single bay garage</li> <li>Missing LUS24 on trusses in dining area</li> <li>Truss screws in dining area not installed through second top plate (correct)</li> <li>Missing hangers on joists in great room/ foyer</li> <li>Fb top of HVAC chase into foyer main floor</li> <li>Header off joist landing on non load bearing wall owner entry/ kitchen</li> <li>HVAC chase into foyer</li> <li>Provide security blocking at front door</li> <li>Provide hold own for double girder truss in bedroom 2</li> <li>Provide support under basement stairs landing rim joist on open side</li> </ul>			
		- FYI broken glass in ba	sement Egress windov	v	

**Comments:**