## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## OnlinePortal at DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #: PRRES20245069

Address: 2615 SW FIREFLY LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date: Monday, July 07, 2025 **Erosion Control Inspection** Dustin Agcopra Failed Residential Corrective Action Required: DEFICIENT EROSION CONTROL INSTALLATION. RESTOREE EROSION CONTROL 1 DCM2 ESC DEFICIENT ALONG THE STREET AND GRAVEL AT LOT ENTRY INSTALLATION NO FURTHER INSPECTIONS UNTIL ADEQUATE EROSION CONTROL PROVIDED. Corrective Action Required: DCM3 ESC 7-7-25 Dustin A, No ESC is in place and silt is covering sw. EROSION CONTROL REQUIRED 2 DAY REQUIRED. EROSION CONTROL SHALL BE IN COMPLIANCE WITHIN TWO **BUSINESS DAYS.** 

**Comments:**