



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRSUBD20210354, Public Infrastructure

Address: 2101 SW M 150 HWY, LEES SUMMIT, MO 640823902 SW PRYOR RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
PW Bond Inspection	Bob Burns	Failed	Wednesday, July 09, 2025

Corrective Action Required

1 Misc

Bond Inspection - There are multiple areas in the pavement on SW Clayton, and SW Osage that have settled. I will schedule an onsite meeting with Development Services to go over the issues. The road issues will need to be repaired.

Comments: