



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRSUBD20210354, Public Infrastructure

Address: 2101 SW M 150 HWY, LEES SUMMIT, MO 640823902 SW PRYOR RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
PW Bond Inspection	Matt Munger	Failed	Monday, July 14, 2025

Corrective Action Required

1 Misc

Bond Inspection - we met onsite with Ryan H. with Development and a representative from Emery Sapp. We walked the subdivision and marked out the areas of pavement that were of concern. Emery Sapp will work through the Dev Services to make these repairs. Areas of concern listed below.

2125 SW Rutherford
2204 SW Osage across the street from address
2133 SW Osage
Intersection SW Osage and SW Clayton
3722-3740 SW Clayton has multiple areas that have settled.

Comments: