CITY OF LEE'S SUMMIT

Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

STOP WORK ORDER

ANY UNAUTHORIZED PERSON REMOVING THIS NOTICE WILL BE PROSECUTED

Permit #: PRRES20242665

Address: 3804 SW RAVENGATE PL, LEES SUMMIT, MO 64082

Any person who shall continue work after having been served with a stop work order, except such work as that person is directed to perform to remove a violation or unsafe condition, shall be subject to penalties as prescribed by law.

Inspection: Outcome: Date:

Erosion Control Jamie Simerly Failed - Stop Work Friday, July 18, 2025

Inspection Residential

Corrective Action Required

1 DCM1 ESC REQUIRED NO 5/13/25

FURTHER INSP EROSION CONTROL REQUIRED. NO FURTHER INSPECTIONS WILL

BE PERFORMED UNTIL EROSION CONTROL IS INSTALLED AND IN

COMPLIANCE.

-Install erosion control methods at perimeter, properly protect

storm inlet

Corrective Action Required

DCM3 ESC REQUIRED 2 07/15/25 Jamie S, Erosion control needs to be reestablished.

DAY Erosion control needs to be added to front right corner of variables.

Erosion control needs to be added to front right corner of yard as well due to soil going over sidewalk and driveway. All of the sidewalk needs to be cleaned off and free of debris to prevent safety hazards. Silt socks in front of storm drains on both

Ravengate PI and Osage Dr need to be cleaned out.

EROSION CONTROL REQUIRED. EROSION CONTROL SHALL BE IN

COMPLIANCE WITHIN TWO BUSINESS DAYS.

07/18/25 Jamie S, Erosion control needs to be reestablished. Erosion control needs to be added to front right corner of yard

220 SE Green Street | Lee's Summit, MO 64063 | 816.969.1200 Page 1

CITY OF LEE'S SUMMIT

Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

as well due to soil going over sidewalk and driveway. All of the sidewalk needs to be cleaned off and free of debris to prevent safety hazards. Silt socks in front of storm drains on both Ravengate Pl and Osage Dr need to be cleaned out.

Comments: