

Facility: Lee's Summit Medical Center Project: Medsurg & Dietary Expansion

DGL Project No: 6406.24.0001

Date: 06/06/2025

Ticuiticuic				
ADDENDUM "1" DESIGN COORDINATION				
#	Sheet #	Revision Narrative		
STRUCTURAL				
1	S120	Added angular dimension to the pedestrian bridge per RFI response.		
2	S123A	Added lightweight self-leveling underlayment to the slab.		
3	S123B	Added lightweight self-leveling underlayment to the slab.		
4	S124B	Added column size callouts per RFI responses.		
5	S302	Detail 11: Added for level compound termination at slope.		
6	S501	Detail 3: Added information related to the existing column stub up height.		
ARCHITECTURAL LIFESAFETY				
1	AC103	Revised per added slopes and door relocation.		
ARCHITECTURAL				
1	GI000	Added submittal titles and date for Design Coordination.		
2	GI001	Updated sheet index.		
4	AE103	Revised per door relocation at Corridor (3-COR7) and Equipment Storage (3-2083)		
5	AE123A	Revised dimensions per door relocation at Corridor (3-COR7).		
6	AE123B	Revised per door relocation at Equipment Storage (3-2083)		
7	AE133A	Revised per relocated doors and added floor slopes.		
8	AE133B	Revised per relocated doors and added floor slopes.		
9	AE143	Revised per added topping slab, added new elevation tag.		
10	AE183A	Dimensions for topping extents. Revised ceiling condition by relocated doors area.		
11	AE202	Revised per new added Level 3 - Topping		
12	AE203	Revised per new added Level 3 - Topping		
13	AE302	Revised per new added Level 3 - Topping		
14	AE303	Revised per new added Level 3 - Topping		
15	AE312	Revised per new added Level 3 - Topping		
16	AE401	Revised per added slopes.		
17	AE502	Revised details 1/AE502 & 2/AE502 per slab topping		

MECHANICAL			
1	MD02-03A	Updated floor plan to show additional demolition of ductwork.	
2	MD02-03B	Updated floor plan to show additional demolition of ductwork.	
3	M02-03A	Updated ductwork routing and sizing to accommodate for new topping slab. Shifted Smoke Dampers to align with shifted door locations.	
4	M02-03B	Updated ductwork routing and sizing to accommodate for new topping slab.	
5	M03-03A	Shifted thermostat and pressurization arrow to align with shifted door location in EVS.	
ELECTRICAL			
1	E02-01	Relocated 'M1ELKB' from Elec Room 1-ME1072 to Elec Room 1-1303.	
2	E02-03A	Revised outlet location in EVS to align with shifted door location.	
3	E02-03B	Revised plug mold location in Equiment Storage to align with shifted door location.	
4	E03-03A	Revised exit signs and switch locations to align with shifted door locations.	
5	E03-03B	Revised light switch in Equiment Storage to align with shifted door location.	
6	E04-03A	Revised smoke detectors and door holds locations to align with shifted door locations.	
7	E05-01	Relocated 'M1ELKB' from Elec Room 1-ME1072 to Elec Room 1-1303.	
8	E06-05	Updated the size of ATS-M1EC, M1DPEH3, and associated feeders.	
TECHNOLOGY			
1	T02-03A	COMM sleeve locations revised to align with shifted door locations.	
2	T02-03B	Added Data outlet at Nurse Alcove 3-2086E	
3	T03-03B	Added EP Nurse Call device in TLT 3-2068	