

#### **DEVELOPMENT SERVICES**

# Minor Plat Applicant's Letter

Date:	Monday, December 20, 2021			
То:	: Property Owner: COLBERN ROAD INVESTORS LLC		Email:	
Applicant: MAT		TT SCHLICHT	Email: MSCHLICHT@ES-KC.COM	
	City Staff: Scott Ready		Email: Scott.Ready@cityofls.net	
From: Shannon McGuire, Planner Re:				
Application Number:		PL2021457		
Application Type:		Minor Plat		
Application Name:		Colbern Road Investments Lot 2		
Location:		900 NE COLBERN RD, LEES SUMMIT, MO 64064		

## **Electronic Plans for Resubmittal**

All Planning application and development engineering plan resubmittals shall include an electronic copy of the documents as well as the required number of paper copies.

Electronic copies shall be provided in the following formats

- Plats All plats shall be provided in multi-page Portable Document Format (PDF).
- Engineered Civil Plans All engineered civil plans shall be provided in mulit-page Portable Document Format (PDF).
- Architectural and other plan drawings Architectural and other plan drawings, such as site electrical and landscaping, shall be provided in multi-page Portable Document Format (PDF).
- Studies Studies, such as stormwater and traffic, shall be provided in Portable Document Format (PDF).

Please contact Staff with any questions or concerns.

## **Review Status:**

220 SE Green Street | Lee's Summit, MO 64063 | 816.969.1200 | 816.969.1201 Fax | cityofLS.net/Development

# LEE'S SUMMIT

#### **DEVELOPMENT SERVICES**

**Required Corrections:** 

Planning Review	Shannon McGuire (816) 969-1237	Planner Shannon.McGuire@cityofls.net	No Comments
Engineering Review	Sue Pyles, P.E. (816) 969-1245	Senior Staff Engineer Sue.Pyles@cityofls.net	No Comments
Fire Review	Jim Eden (816) 969-1303	Assistant Chief Jim.Eden@cityofls.net	Not Required
Traffic Review	Brad Cooley	Brad.Cooley@cityofls.net	No Comments
Building Codes Review	Joe Frogge	Plans Examiner	Not Required
	(816) 969-1241	Joe.Frogge@cityofls.net	
GIS Review	Kathy Kraemer (816) 969-1277	GIS Technician Kathy.Kraemer@cityofls.net	Corrections

1. Coordinates are incorrect and numbered incorrectly.