CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20245549

Address: 1933 SW MERRYMAN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Erosion Control Inspection Jamie Simerly Failed Thursday, July 31, 2025

Residential

Corrective Action Required:

1 Misc Erosion control in place at time of inspection

Corrective Action Required:

DCM3 ESC 07/31/25 Jamie S, Down stream storm drain needs to be cleaned out. Talked

REQUIRED 2 DAY to Project manager about it.

EROSION CONTROL REQUIRED. EROSION CONTROL SHALL BE IN COMPLIANCE

WITHIN TWO BUSINESS DAYS.

Comments: