

CITY OF LEE'S SUMMIT CODES ADMINISTRATION 220 SE GREEN ST. P.O.BOX 1600

PHONE: 816-969-1200

FAX:

816-969-1201

Inspection Summary

Permit #: PRCOM20120225, Building Permit - Commercial Address: 635 SW 2ND ST, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

In-wall Inspection John Borns Failed Monday, March 19, 2012

Corrective Action Required

1 MISC MECH RM @ SE:

1) FIREBLOCKING AND SHIELD PLATES WITHIN MECH RM NOT REQ'D IF AND ONLY IF NO DRYWALL AT WALLS AND NO

CEILING

2) TRUSS JOIST AT W WALL: BOTTOM CHORD NOTCHED --

ENGINEER REPORT REQUIRED

3) OVERBORED(>60%) NON-BEARING STUDS REQUIRE

REINFORCEMENT

4) PLUMBING SHIELD PLATES AT TOP AND BOTTOM PLATES

MUST BE DEEP BOCA PLATES

Comments: