

## CITY OF LEE'S SUMMIT CODES ADMINISTRATION 220 SE GREEN ST. P.O.BOX 1600

PHONE: 816-969-1200

FAX:

816-969-1201

## **Inspection Summary**

Permit #: PRCOM20120225, Building Permit - Commercial Address: 635 SW 2ND ST, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough John Borns Partial Monday, March 26, 2012

Inspection - Commercial

Corrective Action Required

1 MISC TOPS OF EXTERIOR WALL CAVITIES TO BE FIREBLOCKED TO

PREVENT FIRE COMMUNICATION TO INTERSTITIAL SPACE

ABOVE CEILING

Corrective Action Required

2 MISC FIREBLOCKING REQUIRED AT 10' HORIZONTAL INTERVALS TO

PREVENT FIRE TRAVEL WITHIN EXTERIOR WALLS

Corrective Action Required

3 MISC BOCA PROTECTION PLATES REQUIRED AT PVC PLUMBING

STACK

Comments: OK TO INSULATE EXTERIOR WALLS AND ABOVE GWB CEILINGS. OK TO INSTALL GWB AT INTERIOR WALLS AFTER BOCA PLATES ARE IN PLACE PER ABOVE.