## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## OnlinePortal at DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #: PRRES20251603

Address: 2090 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

**Erosion Control Inspection** Robb Popp Failed Thursday, September

Residential 11, 2025

Corrective Action Required:

1 DCM2 ESC 9/11/25

DEFICIENT DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS

INSTALLATION UNTIL ADEQUATE EROSION CONTROL PROVIDED.

-Maintain storm inlet

-Provide erosion control methods

## **Comments:**