CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20243308

Address: 2601 SW PRYOR RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Erosion Control Inspection Tyler Schreck Failed Monday, September

22, 2025

Corrective Action Required:

1 PW-Erosion and Your project is in violation of the Erosion and Sediment control policy.

Sediment Control 9/22/25 Tyler S. There is not erosion control on site. I talk to the foreman Jason with Randy Spalding and he ensured me that it will be up tomorrow 9/23/25. Failure to do so could result in a STOP WORK order issued until we

are in compliance. Erosion control must be in place and maintained

throughout construction.

Comments: